# FE251

Diagram No. 8102-3

NOAA FORM 76-35A

U.S. DEPARTMENT OF COMMERCE
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SURVEY

## DESCRIPTIVE REPORT

Type of Survey Field Examination  RA-5-2-83  Field No. FE-251
LOCALITY
State Alaska
General Locality Tongass Narrows
Locality Ward Cove
Locally
1983
CHIEF OF PARTY LCDR D.W.Yeager
LIBRARY & ARCHIVES
DATE July 5, 1984

☆U.S. GOV. PRINTING OFFICE: 1980-766-230

CHTS:
17420 INSET 3 to Record of Type of the

AAON	F	ORM	77-28
(11 - 72)	1		

### U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION

REGISTER NO.

### HYDROGRAPHIC TITLE SHEET


FE-251

INSTRUCTIONS - The Hydrographic Sheet should be accompanied by this form, filled in as completely as possible, when the sheet is forwarded to the Office.

FIELD NO.

RA-5-2-83

Alaska State		
General locality Tongass Narrows		
Locality Ward Cove		
Scale 1:5,000	Date of survey	Sep. 27 - Oct. 27, 1983
Instructions dated September 14, 1983		
Vessel NOAA Ship RAINIER Launches 2124 and		
ICDD D W Vascan		
Soundings taken by echo sounder, hand lead, ****		
Graphic record scaled by Ship's Personnel		
Graphic record checked by Ship's Personnel		*
Verified R. Davies		
Evaluated by J. Green		
	and tenths of	
REMARKS: Revisions and marginal notes in bl	ack are by	the evaluator.
SURF Checket	2 3/51	\$5 STV
1//	2.11/2	et/
SURF PHIALA	<u> </u>	<u> </u>
SUFF CALCAL	- 2/5/8	
SUFF CHURA		



### A. PROJECT

This field examination was conducted in accordance with Project Instructions S-0907-RA-83, Ward Cove, Ketchikan, and Metlakatla, Alaska, dated September 14, 1983. The purpose of this field examination was to investigate a specific area of concern in Ward Cove, Alaska, as noted by the Southeastern Alaska Pilots' Association and in the U.S. Coast Pilot Field Reports.

### B. AREA SURVEYED

This field examination was conducted in Ward Cove, north of 55° 24.2'N and west of 131° 43.3'W between Julian Date 270 and Julian Date 319 (September 27 and November 15, 1983).

The Ketchikan Pulp Mill (Louisiana-Pacific, Ketchikan Division) and associated log storage areas are within the limits of the area of this examination.

### C. SOUNDING VESSEL

All echo soundings were obtained by RAINIER hydrographic survey launches RA-4 (2124) and RA-5 (2125). All bottom samples were obtained by RA-5. No unusual sounding vessel configurations or problems were utilized or encountered.

### D. SOUNDING EQUIPMENT AND CORRECTIONS TO ECHO SOUNDINGS

Echo soundings obtained during this field examination were collected by the specified launches and both were equipped with Ross Fineline Fathometer systems. These systems include the following Ross components: Model 4000 transceivers, Model 5000 analog trace recorders, Model 6000 digitizers and 100 Khz transducers. Table I summarizes the serial numbers of these components:

TABLE I

Echo Sounding Component Serial Numbers

Launch	2124	2125
Transceiver	1080	1042
Analog	1071	1040-6
Digitizer	1040	1042

Analog recorder #1071 occasionally failed to advance the paper at a constant rate. No peaks were missed due to this problem.

A problem in the Hydrolog system in RA-5 (2125) developed which occassionally caused "short" marks to appear on the analog trace where none were required. When this problem occurred, in-between soundings were scaled and compared with the digital depths. No soundings were missed due to this problem.

Sound velocity corrections, were determined from an STD cast taken on October 27, 1983 during OPR-0168-RA-83 (see Echo Sounding Report for OPR-0168-RA-83). Copies of the graph, velocity table and a listing of the velocity tape are provided in the separates following the text. The smooth field sheet was prepared using these velocity correctors.

See Eval Report Sect1b

The smooth field sheet was prepared using the launch historical TRA value of 0.3 fathoms, for both RA-4 and RA-5. Copies of the bar check abstracts are provided in the separates following the text.

Launch settlement and squat determinations were conducted on February 14, 1983 at Shilshole Bay, Puget Sound, Washington. No correctors for settlement and squat have been applied to the smooth field sheet. All soundings were obtained at a speed (700 RPM) for which the correctors are zero. A copy of the results of the settlement and squat determinations are provided in the separates following the text. (Filed with field of coords)

During survey operations, the blanking depth was set to a value shoaler than the shoalest bottom expected. Analog depths were substituted for missing or erroneous digital depths as part of standard scanning procedures.

. /

The initial trace on the analog recorders was maintained at zero. Corrections for variation of the initial were applied during scanning.

Phase calibrations and belt tension checks were performed in accordance with section 4.9.6 of the <u>Hydrographic Manual</u>, Hydrographic Survey Guidelines and PMC OPORDER, Appendix B.

All soundings on the smooth field sheet have been corrected for predicted \( \sqrt{tides.} \) Ketchikan, Alaska served as the reference station for the predicted tides.

Manual soundings were obtained by use of a hand-held lead line where required. Depth markings on the lead line were compared with a steel measuring tape prior to survey operations and were found to be accurate. More details on the corrections in this section can be found in the Corrections to Echo Soundings Report, OPR-0168-RA-83.

### E. HYDROGRAPHIC SHEET

Field sheet RA-5-2-83 was prepared on the RAINIER using the PDP 8/e Hydroplot system which produces modified, transverse Mercator projection. A list of parameters used to define the hydrographic sheet are provided in the separates following the text. All field records will be sent to the Pacific Marine Center, Seattle, Washington. The smooth field sheet is plotted on a page-size mylar and is included with this report.

### F. CONTROL STATIONS

All control stations utilized were existing Third-Order, Class I geodetic stations on the North American 1927 Datum.

### G. HYDROGRAPHIC POSITION CONTROL

Range/Azimuth was the only method used for sounding line position control. Motorola Mini-Ranger positioning systems and a Wild Theodolite (S/N 65516) were used. The tables below summarize the location of all Mini-Ranger mobile and shore equipment:

### TABLE II

### Mini-Ranger Mobile Equipment

Vessel	Console S/N	R/T S/N
2124	В 0269	В 1388
2125	715	в 1108

### TABLE III

### Mini-Ranger Shore Equipment

Code	Transponder S/N	Station No.
В	4951	103
D	1569	103

The smooth field sheet was plotted using correctors determined from the initial baseline calibration. For more information concerning calibrations, refer to the Electronic Control Report, OPR-0168-RA-83.

System checks were performed daily. These checks were accomplished by the static calibration method.

Mobile and shore equipment performed very well and the calibration data  $\sqrt{\ }$  as applied to the smooth field sheet are adequate.

A copy of the Abstract of Corrections to Electronic Position Control is provided in the separates following the text.

### H. SHORELINE

The shoreline on the smooth field sheet was transferred from shoreline map T-10597 (unregistered, scale 1:10,000) enlarged to a scale of 1:5,000. All shoreline from this map is shown in brown on the smooth field sheet.

During this examination, a discrepancy was found between the shoreline as shown on the above map and the actual shoreline. The area is west of the pulp mill and is shown in red on the field sheet. The source of this shoreline was a blueprint of the area supplied to the RAINIER by the senior engineer at the pulp mill (see Miscellaneous Information section in separates following text for names and addresses of pulp mill officials). The pulp mill obtained the shoreline position from an aerial photograph in their possession. This area has been completely filled and reclaimed. The shoreline blueprint is included with the survey records.

No other shoreline discrepancies were noted during this field examination. Refer to section Q for an additional discussion of the shoreline in this area.

### I. CROSSLINES

Crosslines account for 44% of the total mileage run in Ward Cove. In all cases, crossline agreement is excellent.

### J. JUNCTIONS

Junction surveys are not applicable to this field examination.

### K. COMPARISON WITH PRIOR SURVEYS

Three presurvey review items were within the limits of this field examination.

### Item No. 50606

This item called for a bottom drag investigation of the wreck charted at  $55^{\circ}$  24' 21.36"N and  $131^{\circ}$  43' 23.48"W. At the time of this field examination an anchored house float was located at this position, making a bottom drag impractical. It is recommended that this item remain as charted.

This item called for investigation of a 3.0 fm shoal at 55° 24' 26.4"N,

This item called for investigation of a 3.0 fm shoal at 55° 24° 26.4"N, 131° 43' 24.0"W created by an earth slide during construction of the pulp mill pier.

See Exal Report Sect 2

See Eval Report Sect 5

See Eval Report, Sect 6 The shoal was verified by echo sounder and lead-line investigation.

Lead-line soundings were obtained along the face of the pulp mill pier. These soundings indicate a shoal area at the eastern end of the pier. Officials of the mill assured the field party that they are aware of this shoaling and that no ships are allowed to dock that far down the pier. This area is used only for unloading of "chip barges". Spilling of the chips is the cause of the shoaling. It is recommended that the soundings from the present survey be used to update this area of the chart.

### Item No. 50608

This "information" item described shoaling on the 30 foot depth curve by fill from behind the face of the wharf. A least depth of 3.5 fm was found at 55° 24' 25"N, 131° 43' 29.5"W. See Item 50607 for shoaling at the east end of this pier.

See Eval Report, Sect 6

Prior surveys, H-7869 (1951) and wire drag survey H-8101 (1953), were compared to the present field examination. Both surveys were done at a scale of 1:5,000.

See Eval Report, Sect 6

Comparison of this field examination with survey H-7869 shows a general shoaling trend, averaging 1.0 to 2.0 fm throughout the area.

 $\checkmark$ 

Survey H-7869 was conducted in 1951, prior to the beginning of operation of the pulp mill. Operation of the mill is the most probable cause of the shoaling trend in this area. Officials of the mill stated that pieces (and sometimes entire logs) sink in the area and accumulate on the bottom. Also, bottom samples taken during field work indicate that the bottom is primarily made up of small wood chips.

/

The most notable shouling appears in the northwest corner of the area. There are two sewage outfalls in this area from the treatment plant associated with the pulp mill which may be a contributing factor to the shouling in this area.

Comparison of this field examination with wire drag survey H-8101 showed good overall comparison with no significant differences.

See Evol Report, Sect. 6

### L. COMPARISON WITH THE CHART

This field examination was compared to NOS Chart No. 17428, 4th Edition, February 1980, 1:10,000 scale enlarged to a scale of 1:5,000. This comparison also indicates a general shoaling trend in the area.

 $\sqrt{\phantom{a}}$ 

The major shoaling occurs in the western and northeastern portions of the area. The 10 fathom depth curve extends up to 50 yards farther offshore than charted in the western portion of the area investigated. In the northeastern area of this examination, the 10 fathom curve is no longer configured as charted. This curve presently extends as far as 350 yards south of its charted position.

It is recommended that the soundings obtained by this field examination supersede those previously charted in this area.

The charted dolphins at positions 55° 24' 21"N, 131° 43' 45"N and 55° 24' 22"N, 131° 43' 40"W should be deleted from the chart. The senior engineer of the pulp mill stated that he personally supervised the removal of these dolphins and that they were totally removed.

The disposal area charted at approximately 55° 24.2'N and 131° 43.6'W is See Eval no longer active. This information was obtained from officials of the pulp mill. It is recommended that this symbol be deleted from the chart. Other charted features and recommendations are discussed in section 1/2.

### ADEQUACY OF SURVEY

This field examination is complete and sufficient to supersede all prior surveys for charting purposes except as noted in sections-M and Q.

### AIDS TO NAVIGATION

No aids to navigation exist in the area of this field examination.

### STATISTICS

	Linear	Square	Number
Survey Launch	Nautical Miles	Nautical Miles	of Positions
RA-4 (2124)	2.93		130 138
RA-5 (2125)	0.67		27 157 165
Total	3.60	0.12	157 165
			•

Bottom Samples:

### MISCELLANEOUS

No anomalous currents were observed during field work and none were indicated during conversations with local inhabitants of the area.

This area was difficult to survey due to the logging activities of the pulp mill. The log booms within which logs are stored are not permanently placed. Their location is changed by the tides as well as by employees of the mill. A "holiday" exists on this field examination at approximately  $55^{\circ}$  24.2'N and  $131^{\circ}$  43.5'W due to these booms.

See Eval Report. Sect ?

See Evol Report Sect 6 87

It is recommended that a note be added to the chart to caution mariners of the variability of the locations of these log storage areas. Photographs of the area are included in the separates following the text.

Concur

### Q. RECOMMENDATIONS

It is recommended that this area be scheduled for aerial photography prior to the next edition of the chart. As stated in section H, there have been changes to the shoreline since the last photographs were compiled. Also, there is a dike project being conducted on the eastern shore of Ward Cove, south of Ward Creek, which will change the shoreline in this area.

Concur

There are no further recommendations other than those previously stated in sections K, L, and P.

### R. AUTOMATED DATA PROCESSING

Data acquisition and processing were accomplished in accordance with the <u>Hydrographic Manual</u> (Fourth Edition, 1976), Manual of Automated Hydrographic Surveys, the PMC OPORDER, Hydrographic Survey Guidelines and the Hydrographic Data Requirements for 1983.

V

Soundings and positions were taken by an ASI Logger and a Hydroplot system using Range/Azimuth program FA181. There are daily master tapes and corresponding corrector tapes which include the TRA for the launches and electronic control baseline correctors for Mini-Ranger consoles and R/T units and all depth corrections. Velocity tapes were generated from a sound velocity, temperature, depth (STD) cast. The following is a list of all computer programs and version dates used for data acquisition or processing:

/

	PDP 8/e Programs	Version Dates
FA181	Range/Azimuth Hydrolog	2/23/78
RK201	Grid, Signal and Lattice Plot	4/18/75
RK212	Visual Station Table Load	4/01/74
RK216	Range/Azimuth Non-Real Time Plot	2/09/81
RK300	Utility Computations	10/21/80
RK330	Reformat and Data Check	5/04/76
PM360	Electronic Corrector Abstract	2/02/76
RK407	Geodetic Inverse/Direct Computation	9/25/78
AM500	Predicted Tide Generator	11/10/72
RK561	H/R Geodetic Calibration	12/01/82
AM602	Elinore-Line Oriented Editor	12/08/82
RK606	Tape Duplicator	8/22/74

	PDP 8/e Programs	Version Dates
AM607	Self-Starting Binary Loader	8/10/80
RK610	Binary Tape Duplicator	12/01/82
RK612	Line Printer List	3/22/78
RK900	Plot Test Tape Generator For AM902	5/07/76
PM901	Core Check	3/01/72
AM902	Real Time Checkout	11/10/72
DA903	Diagnostic-Instruction Timer	2/27/76
RK905	Hydroplot Controller Checkout	3/18/81
RK935	Hydroplot Hardware Tests	3/15/82
RK950	Hardware Tests (Documentation Only)	6/02/75

The HP-9815 and HP-97 calculators were used to compute geographic positions of electronic control and visual stations and velocity of sound corrections for the plotting of smooth field sheets.

### S. REFERRAL TO REPORTS

The following reports contain information related to this survey:

Echo Sounding Report
Electronic Control Report
Coast Pilot Report

OPR-0168-RA-83 OPR-0168-RA-83 OPR-0168-RA-83

Respectfully submitted,

Joyce L. Judson

ENS, NOAA

## PARAMETER TAPE LISTING RA-5-2-83 FIELD EXAMINATION

WARD COVE, ALASKA

SKEW: 0.10,10 FEST=10000 CLAT=6130000 CMER=131/41/0 GRID=15 PL3CL=5000 PLAT=55/24/00 PLON=131/44/10 VESNO=2124 YR=83 ANDIST=0.00

SKEW: 90,3,10 FEST=10000 CLAT=6130000 CMER=131/41/0 GR1D=15 PLSCL=5000 PLAT=55/24/00 PLON=131/43/10 VESNO=2124 YR=33 ANDIST=0.0

### FIELD TIDE NOTE

Field tide reduction of soundings for RA-5-2-83, Ward Cove, was based on predicted tides from Ketchikan, Alaska (945-0460). Corrections were obtained from Preliminary Tidal Zoning OPR-0168-RA-83. The predicted tides were derived using program AM500.

The reference station at Ketchikan was leveled at the beginning of survey operations on September 22, 1983. Three permanent benchmarks (including the primary mark) were connected to the ETG reading mark. Final levels were run on November 14, 1983. Initial and final levels compared favorably.

One subordinate tide station provided data for this survey. A bubbler tide gage was installed on September 24, 1983 at the historical site on Vallenar Point (945-0511), 55°25.6'N, 131°50.8'W. Three permanent benchmarks were recovered and two benchmarks were established at this location. Initial levels were run on September 24, 1983. The staff value of the zero line on the analog tide record is +12.62 feet. The gage operated well throughout the time of hydrography except for a period of 18 hours on J.D. 298 when a gap in the record occurred due to a paper jam. Final levels for this gage were run on November 15, 1983. Comparison of initial and final levels indicated that no significant movement of the staff occurred during the survey period. The time meridian used for records annotation was 0° (UTC).

NOAA FORM 76-155	ATIONAL (	DCEANIC			ENT OF C			RVEYN	UMBER	
GEC	GEOGRAPHIC NAMES						FE	<b>-</b> 251		
Name on Survey	/a°	L CHART NO C	previous e	UP NET DE STORE	AMOLE ON ORMAN E	on in	P.O. GUIDE	DR MAP	J. Light	,s <sup>1</sup>
ALASKA (title)										1
BOLLES LEDGE	х								х	2
WARD COVE	x								х	3
WARD COVE (locality)	х								х	4
TONGASS NARROWS (title	)	ļ								5
					· · · · ·					6
										7
•										8
										9
										10
										11
										12
				ļ 						13
			<u> </u>							14
										15
										16
										17
					Approv	edi.		• • • • • • • • • • • • • • • • • • • •		18
					- n		,,,			19
						7	. Han		т .	20
					unier	beograp	her - N	1ch23	5	21
					22	MARCH	1984			22
										23
	-								ļ	24
										25

VELOCITY TAPE LISTING RA-20-2-83 (H-10115) RA-20-3-83 (H-10118)

### TABLE NO. 7

000055 0 0000 0007 001 000000 000000 000129 0 0001 000198 0 0002 000262 0 0003 000331 0 0004 000395 0 0005 000469 0 0006 000543 0 0007 000617 0 0008 000696 0 0009 000780 0 0010 000874 0 0011 000973 0 0012 001072 0 0013 001460 0 0015 001950 0 0020 002425 0 0025 002920 0 0030 003435 0 0035 999999 0 0040

## TC/TI TAPE LISTING RA-5-2-33 WARD COVE, ALASKA

LAUNCH - 2124(3A-4)

FATHO: 1071

210040 8 3003 3007 270 212430 0003000 22300 0.0 0 271

LAUNCH - 2125(RA-5)

FATHO: 1040

202557 3 6363 3367 336 212566 338686

214433 9 2333

210330 0 0 21040° 3 7

### ELECTRØNIC CØRRECTØR ABSTRACT

VESSEL : 2124

SHEET : RA-5-2-83

TIME	4	DAY		PATTERN 1		PATTERN 2
•					<del>+</del>	
	1				,	
210040	1	270	, o	+00000	,	-63476
223500	1		•	+00000	,	+00000
	.*				,	
175227	1	271	.*	-00002	-	-04534
211500	-		*	-00002	-	+00000
	1		•		/	
170930	.*	272	*	-00002	-	-38007
195018	•		•	-00002	1	+00000

DISREGARD PATTERN 2 CØRRECTØRS FØR RANGE/AZIMUTH HYDRØ.

### ELECTRONIC CORRECTOR ABSTRACT

VESSEL : 2125

SHEET : RA-5-2-83

TIME	DAY	~	PATTERN 1		PATTERN 2
	300	, , ,	00001 +00000	/ / / /	-02000 

DISREGARD PATTERN 2 CØRRECTØRS FØR RANGE/AZIMUTH HYDRØ.

## MASTER STATION LIST 5-0907-RA-33 WARD COVE, KETCHIKAN, AND METLAKATLA, ALASKA

### VERSION 11/29/83

100 4 55 23 56544 131 44 26823 139	0001 000000
/DECOY 1951	551313(1052)
103 4 55 24 06655 131 43 09945 250	2023 222003
/BABEL 1951	551313(1010)
104 4 55 24 30433 131 42 59185 139	0202 020220
/WARD COVE HOUSE W GABLE 1951	551313(1220)
105 4 55 23 46541 131 44 39270 139	2022 202000
/ABIDE 1951	551313(1003)
2 <del>81 4 55 19 51236 131 37 59835 258</del>	<u>8031 080337</u>
/HICK 1906	551313(1235)
202 4 55 20 02438 131 37 35032 139	0000 000000
/STANDARD OIL PIER EAST LT	FFAID FILE
203 4 55 2% 24096 131 37 38719 139	0000 000000
/STANDARD OIL PIER WEST LT	FFAID FILE
204 4 55 20 19486 131 38 29770 139	Ø014 Ø00000
/THOMAS BASIN LT 3 1977	G-16105(ADJUSTED)
205 4 55 03 21646 131 34 40941 250	0001 000000
7LUMP 1913	551313(1107)
206 4 55 07 34702 131 32 24345 252	0023 003000
/CAS 1913	551313(1032)
207 4 55 20 22482 131 38 13328 133	0 0036 0000000
/KETCHIKAN RADIO TOWER KTAN 1977	G-16105(ADJUSTED)
208 4 55 07 40553 131 34 31287 139	0000 000000
/METLAKATLA TOWN HALL CUPOLA 1914	551313(1115)
209 4 55 07 38382 131 34 37551 139 ZMETLAKATLA W CHURCH TOWER 1914	0 000
210 4 55 07 53240 131 35 01611 139 /METLAKATLA SREAKWATER LT 2	2000 222822

## ABSTRACT OF POSITIONS RA-5-2-83

Vessel: 2124 (RA-4)

Andist: 0-0

DAYS	POSITIONS	CTRL	<u>S1 M S2</u>	REMARKS
270	4000-4012	11	103-R/AZ	Mainscheme lines
270	4013-4015	11	103-R/AZ	D. P. Floating Dock
270	4016-4033	11	103-R/AZ	Radial Lines
271	4034-4072	11	103-R/AZ	Mainscheme lines
271	4073-4083	11	103-R/AZ	D. Ps. Log Boom
271	1000-1008	13	Manually scaled	Leadline pier face
272	4084-4093	11	103-R/AZ	D. Ps. dolphins & log booms
272	4094-4105	11	103-R/AZ	Radial lines
272	4106	11	103-R/AZ	D. P. S.W. edge of float
272	4107-4118	11	103-R/AZ	Radial lines
272	4119-4129	11	103-R/AZ	D. Ps. log booms
Vessel:	2125 (RA-5)			
Andist:	0-0			
300	5000-5021	11	103-R/AZ	Mainscheme lines
300	5022-5023	11	103-R/AZ	D. P. on shoal
300	5024-5026	11	103-R/AZ	Bottom samples

0.85 FINT Ч h h U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION 11-20-83 (Unusual conditions, cohesiveness, dented cutter, stat. no., type of bottom relief i.e., slope, plain, disposition, etc.) DATE CHECKED BTRONG SEWALE-LIKE OPOCK STRONG SEWACE. LIKE ONCR SHALL SEA URCHIN REMARKS BEB CHECKED BY < 2 mm < 2mm FIELD DESCRIPTION WARD COVE, ALASKA WOOD CHIPS WOOD CHIPS WOOD CHIPS OCEANOGRAPHIC LOG SHEET - M BOTTOM SEDIMENT DATA LENGTH COLOR OF SEDI-CORE MENT 64 bK RA.5.2-83 DEPTH WEIGHT OF SAM-Į. 45 6861 : 550 V (3100E (Fethome) YEAR 24/1.69 43/405 20,8 9 8 24/20.62 433,24 10.7 5-0907-RA. 83 24/1458 43/25,80 SAMPLE POSITION PROJ. NO. Use more than one line per sample if necessary. 10/27/83 50 300 DATE : 2125 : NOAA FORM 75-44 5026 SERIAL NO. 5025 5024 VESSEL

立 U.S.GPO:1980-665-715/1183-6



Ketchikan Division of Louisiana-Pacific Corporation, Ward Cove, Alaska. Note sewage outfall at left and "chip barge" at right-hand (eastern) end of pier.



Note "house float" & "chip barge" at 6 left.

### MISCELLANEOUS



Ketchikan Division

Thomas L. Hogan Senior Engineer

P.O. Box 6600 Ketchikan, Alaska 99901 907/225-2151

Pulp Mill Official



\_\_\_\_

Dan Loitz Plant Engineer

P.O. Box 6600 Ketchikan, Alaska 99901 907/225-2151

Pulp Mill Official



Note "house float" & "chip barge" at 6 left.



Anchored log boom.

### APPROVAL SHEET

### DESCRIPTIVE REPORT TO ACCOMPANY

### HYDROGRAPHIC SURVEY

RA-5-2-83

In producing this sheet, standard procedures were observed in accordance with the Hydrographic Manual, PMC OPORDER, Hydrographic Survey Guidelines, and the 1983 Data Requirements Letter. The data was examined daily during the execution of the survey.

The boatsheet and the accompanying records have been examined by me, are considered complete and adequate for charting purposes, and are approved.

David W. Yeager

Lieutenant Commander, NOAA Acting Commanding Officer

### PACIFIC MARINE CENTER EVALUATION REPORT

REGISTRY NO: FE-251

FIELD NO: RA-5-2-83

Alaska, Tongass Narrows, Ward Cove

SURVEYED: September 27 - October 27, 1983

SCALE: 1:5,000

PROJECT NO: S-0907-RA-83

SOUNDINGS: Ross Model 5000 Fathometer

Leadline

Fathoms and tenths of fathoms

CONTROL: Motorola Mini-Ranger
Range-azimuth

Chief of Party.....Lt.Cdr. D. W. Yeager

Surveyed by......Ens. J. Judson

SST R. Hastings

Automated Plot by......PMC Xynetics Plotter

J. N. Shofner

### 1. INTRODUCTION

FE-251 is a field examination conducted in accordance with Project Instructions S-0907-RA-83, Ward Cove, Ketchikan, and Metlakatla, Alaska, dated September 14, 1983. This Field Examination of Ward Cove at 1:5,000 scale, is bordered to the east by house floats and log storage areas, to the west by a log storage area, to the north by the shoreline. To the south it extends offshore to the 20 fathom depth curve.

During verification the following data were changed:

- a. Plotting parameters were changed to the PMC format and to change the projection to polyconic.
- b. The velocity table was recompiled to correct discrepancies noted in a new HP-97 program for velocity table calculations.
  - c. The TC/TI table was amended to provide for leadline depths.
- d. Tide level values are from observed tides at Tide Station 945-0460, Ketchikan, Alaska zoned to Ward Cove.

Numerous abstracts and supplements not relevant to the user of the processed data were removed from the Descriptive Report and filed with the field records.

### CONTROL AND SHORELINE

Horizontal control and hydrographic positioning are adequately discussed in paragraphs F and G of the Descriptive Report.

The smooth sheet is plotted utilizing published NGS positions on the North American Datum of 1927.

The shoreline shown in brown, for orientation purposes only, originates mostly from unregistered shoreline manuscript T-10597 (1:10,000 scale). Dates of photography and field edit are unavailable. The shoreline shown on the smooth sheet from longitude 131°43'46"W to longitude 131°43'52.5"W is from the field sheet which is based on an engineering drawing (copy with survey records).

#### 3. HYDROGRAPHY

Soundings at crosslines are in good agreement. The standard depth curves could, be adequately drawn, except where additional soundings at latitude 55°24'20"N, longitude 131°46'21"W could have better defined the 5- and 3-fathom curves. Supplementary brown depth curves were added as necessary. The development of the bottom configuration and delineation of least depths is adequate except as follows:

- 3.5 fm sndg at latitude 55°24'15.5"N, longitude 131°43'26.5"W 3.9 fm sndg at latitude 55°24'21"N, longitude 131°43'23"W 6.6 fm sndg at latitude 55°24'21.5"N, longitude 131°43'31.5"W

### CONDITION OF SURVEY

The hydrographic records and final report adequately conform to the requirements of the Hydrographic Manual, 4th Edition, revised through Change 3, except:

- Least depth of shoal indications, as identified in Section 3 of this report, were not determined.
  - The velocity table was initially submitted in error.

#### 5. JUNCTIONS

There are no contemporary junctional surveys bordering on FE-251. The 20fathom depth curve is in fair agreement with charted depths, however, the shoaling as a result of deposits from the pulp mill have resulted in substantial change in the areas of the 10-fathom and shoaler depth curves.

#### 6. COMPARISON WITH PRIOR SURVEY

AWOIS Item 50606 is a sunken barge charted at latitude 55°24'21.36"N, longitude 131°43'23.48"W, as a Wk cleared 6 fathoms 5 feet. The charted position of this item is within the limits of an anchored house float found during this survey, therefore the wreck was not investigated. A shoal depth of 3.9 fathoms was found 35 meters south of the charted wire drag cleared depth, however, the 3.9

is believed to be the result of wood chip deposits. The house float area limits and the 3.9 fathom sounding should be charted in this area, however, the wreck has not been disproven. If the anchored house float is moved the wreck should be recharted with H-8101WD as the source.

AWOIS Item 50608 is an information item noting fill encroaching on the 30 foot depth curve along the entire face of the wharfin the vicinity of latitude 55°24'25"N, longitude 131°43'30"W. The ship's discussion of this item is supplemented as follows: The five fathom depth curve as shown on this survey has moved offshore approximately 10 meters from the charted curve. Outside the charted ten fathom curve, shoaling from wood chip deposits is apparent. This area should be charted according to the present survey.

The hydrographer's discussion of AWOIS Item 50607 is adequate.

FE-251 was compared with the following prior surveys:

a. H-7869 (1951) 1:5,000 H-8101WD (Supplemental Hydrography) (1953) 1:5,000

H-7869 was accomplished prior to construction of the pier facilities in Ward Cove and use of the present log storage areas, which restrict the area coverage of FE-251. The supplemental hydrography on H-8101WD provided coverage of the newly constructed pier facility. A general shoaling trend of 1 to 2 fathoms is apparent throughout the survey area, with several areas, where dumping of wood chips occur, up to 8 fathoms shoaler. The prior 10-fathom depth curve has shifted approximately 300 meters southwestward indicating a gradual filling of Ward Cove from its head seaward. FE-251 is adequate to supersede H-7869 and that portion of H-8101WD containing supplemental hydrography within the area of common coverage.

### b. H-8101WD (1953) 1:5,000

The following areas common with H-8101WD are now shoaler than that cleared on the prior wire drag survey:

- (1) latitude 55°24'15"N, longitude 131°43'26"W
- (2) latitude 55°24'20"N, longitude 131°43'22"W
- (3) latitude 55°24'26"N, longitude 131°43'24"W (AWOIS Item 50607)

Except for the above three areas, the prior wire drag information is consistent with data shown on FE-251.

### 7. COMPARISON WITH CHART

17428 (4th Ed., February 16, 1980)

a. Hydrography - The charted information originates from the above discussed prior surveys and unknown sources. The shoaling trends noted in Section 6 of this report also apply to the comparison with charted depths. All charted features have been adequately investigated and discussed except as follows:

- (1) The dolphins charted at latitude 55°24'21.1"N, longitude 131°43'45"W and latitude 55°24'22"N, longitude 131°43'40"W were not searched for; instead, the hydrographer contacted the senior engineer of the pulp mill who stated that he personally supervised the removal of these dolphins and that they were totally removed. Based upon this statement, I recommend that the dolphins be removed from the chart.
- (2) The disposal area charted at latitude 55°24'15"N, longitude 131°43'36"W should be shown as discontinued with depths updated to 1983.

Dangers to navigation were identified during the preprocessing examination. A copy of the letter to the Coast Guard is attached.

FE-251 is adequate to supersede the charted information for the areas of common coverage.

- b. Controlling Depths There are no controlling depths charted within the limits of the present survey.
- c. Aids to Navigation There are no aids to navigation within the limits of this survey.

### 8. COMPLIANCE WITH INSTRUCTIONS

FE-251 adequately complies with the project instructions except as mentioned in section 4 of this report.

### 9. ADDITIONAL FIELD WORK

FE-251 is a good field examination. Additional field work to develop the shoal indications and the small holiday noted in Section 3 of this report should be accomplished on a non-priority basis. In addition, aerial photography to update the shoreline and log storage areas should be accomplished prior to the next edition of the chart.

Respectfully,


James S. Green


Supervisory Cartographer


May 24, 1984


This survey has been verified and evaluated. I have examined this survey and it meets Charting and Geodetic Services survey standards and requirements for use in nautical charting except as noted in the Evaluation Report. This survey is recommended for approval.

Suce A. Obmstocl Bruce A. Olmstead Senior Cartographer










SCALE 1:5000 EXCESS LEVEL	NG OVERLAY		
2"			55° 24′ 30″
5"	$4^{76}$ , $6^{7}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ , $6^{5}$ ,		55° 24′ 15″
	18 <sup>2</sup> 13 14 15 <sup>5</sup> 13 14 <sup>7</sup> 15 <sup>5</sup> 16 19 <sup>3</sup> 16 <sup>8</sup> <sup>17</sup>	103 BABEL,	1951 <b>△</b> 55° 24′ 00″
. ° 44′ 00″ 131°	43′45″ 131°	43′30″ 131°	43′ 15″
	<b>9</b>		

	TV									
	FE-25I 03-15	84								
	EXCESS SOUNDING	OVERLAY								
	SCALE 1: 5000									
	EXCESS LEVEL	2 OF 3								
0"							5	5°	24'	30"
				78						
		71	7 <sup>7</sup> 6 <sup>6</sup>							
				8 <sup>4</sup> 9 <sup>2</sup>						
		9 <sup>9</sup>	10 <sup>8</sup> 9 <sup>2</sup>		101					
		199	28							
		167 15						- C 0	2/. /	15"
5"		13 <sup>1</sup> / <sub>12</sub> <sup>1</sup> 13 <sup>5</sup>	16 <sup>5</sup> 15 <sup>4</sup>	3				05	24	15"
		13° 13³ 13 <sup>4</sup>	15 <sup>9</sup> 17 <sup>4</sup>	15 <sup>6</sup>						
		18 <sup>2</sup>								
			177							
						N7 DODE!	1051			
					10	3 BABEL,	1951			
ŀ										
o"							Ę	55°	24'	00"
1 ° 444 ′ 0	00″ 131°	43′ 45″	131°	43′ 30	) <b>"</b>	131 °	43'	15"		



## U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION NATIONAL OCEAN SERVICE

### TIDE NOTE FOR HYDROGRAPHIC SHEET

Marine Center: Pacific

OPR: 0907

HYDROGRAPHIC SHEET: FE-251

Locality: Ward Cove, Alaska

Time Period: September 27 - October 27, 1983

Tide Station Used: 945-0460 Ketchikan, Alaska

Plane Of Reference (Mean Lower Low Water): 6.23 feet

Height Of Mean High Water Above Plane Of Reference: 14.5 feet

Remarks: Recommended Zoning:

For the survey area located within the following boundaries; Latitude  $55^{\circ}25.0'$ , Latitude  $55^{\circ}24.0'$ , Longitude  $131^{\circ}44.0'$ , and Longitude  $131^{\circ}43.0'$ . Apply x 1.03 range ratio to all heights.

Chief, Tidal Datum Section



U.S. DEPARTMENT OF COMMERCE
National Oceanic and Atmospheric Administration
National Ocean Service
Pacific Marine Center
1801 Fairview Avenue East
Seattle, Washington 98102-3767

N/MOP21:MRK

Commander (OAN)
Seventeenth Coast Guard District
P. O. Box 3-5000
Juneau, Alaska 99802

Dear Sir:

*,*;,

During preliminary office review of the field examination in Ward Cove, Tongass Narrows, Alaska, general shoaling was noted in the area and is considered a danger to navigation. Questions concerning the survey may be directed to Capt. Ned C. Austin, Chief, Nautical Chart Branch, telephone (206) 527-6835.

The following statements are recommended for inclusion in the Local

"In Ward Cove, Fongass Narrows, north of latitude 55°24'10", and west of longitude 131°43'20", general shoaling has occurred. Depths are 1 to 3 fathoms shoaler than charted. Shoal depths (MLLW based on predicted tides) were found at the following positions:

4.9 fathoms at latitude 55°24'15.5"N, longitude 131°43'26.5"W, 4.0 fathoms at latitude 55°24'20.7"N, longitude 131°43'23.5"W, 6.7 fathoms at latitude 55°24'21.7"N, longitude 131°43'31.5"W (Chart 17428)."

"An uncharted shoal covered by 1.9 fathoms (MLLW based on predicted tides) is at latitude 55°24'27", longitude 131°43'25.5", at the face of the pulp mill pier in Ward Cove, 33 yards from the NE end. At the NE end of the pier, latitude 55°24'27.7", longitude 131°43'24", is a shoal covered by 0.9 fathoms (MLLW based on predicted tides) (Chart 17428)."

Sincerely,

Charles K. Townsned Rear Admiral, NOAA

Director, Pacific Marine Center



### ATTACHMENT TO DESCRIPTIVE REPORT FOR FE-251

I have reviewed the smooth sheet, accompanying data, and reports of this hydrographic survey. Except as noted in the Evaluation Report, the hydrographic survey meets or exceeds Charting and Geodetic Services (C&GS) standards, complies with instructions, and is accurately and completely represented by the smooth sheet and digital data file for use in nautical charting.

Chief, Nautical Chart Branch (Date)

CLEARANCE:

N/MOP2:LWMordock

SIGNATURE AND DATE:

After review of the smooth sheet and accompanying reports, I hereby certify this survey is accurate, complete, and meets appropriate standards with only the exceptions as noted above. The above recommendations are forwarded with my concurrence.

Director, Pacific Marine Center (Date)

DEPARTMENT OF COMMERCE
National Oceanic and Atmospheric Administration
National Ocean Survey

National Ocean Survey Washington, D.C.

Hydrographic Index No. 110K FE-251 NOXIO OF INDEX Y 962-1 Diagram No. 8201-3 GULF

### NAUTICAL CHART DIVISION

### RECORD OF APPLICATION TO CHARTS

FE-251 FILE WITH DESCRIPTIVE REPORT OF SURVEY NO.

### **INSTRUCTIONS**

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart.

1. Letter all information.

2. In "Remarks" column cross out words that do not apply.

3. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Revi nade under "Comparison with Charts" in the Review.

CHART	DATE	CARTOGRAPHER	REMARKS
7428	1-23-95	Thomas Franking	Full After Verification Review Inspection Signed Via
Inset		-	Drawing No. 7 Applied to Ward Cove Insert. No correction on
		111	main pane due to scale 2/2/95 DC Full Partier After Verification Review Inspection Signed Via
7428	1-17-97	aug Ju	Full Paragraph Arter Value and Review Inspection organic
7428 hvd Cove Inset	1-17-97	Margete	Drawing No. 8 Re-application of source. 1-17-97-wgs
		//	Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
•			
	<u> </u>		
	1		